



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

NMOC

OCT 16 2019

DISTRICT III **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 10.16.19 Operator Cross Timbers API #30-0 39.06647

Property Name Breech E Well No. 109 Location: Unit 3 Section 3 Township 26 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 92 Intermediate 11A Casing 103 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		102		
10 min	0		102		
15 min	0		102		
20 min	0		102		
25 min	0		102		
30 min	0		102		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 11A

REMARKS:

Puff when opened - nothing when opened after
5 min shut in

By Jeff Vagon
Production Foreman
(Position)

Witness Monica Kuehling
Test 6 months - 1 year

E-mail address jvagoner@ctfieldsvcs.com