



NEW MEXICO DEPARTMENT OF
NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/26/19 Operator Blackhawk Energy Corp API #30-0 39-24309
Property Name Jic 464 Well No. 5 Location: Unit B Section 31 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 16 Intermediate Casing 13 Bradenhead -3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>13</u>		
10 min	<u>0</u>		<u>13</u>		
15 min	<u>0</u>		<u>13</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD -1 INTERMEDIATE

REMARKS:

BH showed a negative 3 on gauge a very small suction when opened nothing else through out Test. Casing held 13 psi throughout Test. BH showed a negative 1 after 5 min shut in nothing else

By Robert Talamante

Witness

Plant/lease operator
(Position)

E-mail address rtalamante@blackhawkenergycorp.com

DISTRICT III