



NEW MEXICO DEPARTMENT OF REVENUE
25 EASTERN, DES MOINES, IOWA 50319

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/21/2019 Operator Black hawk energy API #30-0 39-25787
Property Name JIC 459-20 Well No. 8 Location: Unit K Section 20 Township 30 Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 25 Intermediate Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		5			Steady Flow	
10 min	0		5			Surges	
15 min	0		5			Down to Nothing	
20 min						Nothing	✓
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH had 0-psi on guage, nothing else
Casing had 5 psi, and held.
BH had 0 psi after 5 min Shut in nothing else
By Robert Talamante Witness
plant/lease operator
(Position)

E-mail address rtalamante@blackhawkenergy corp. com

SEP 10 2019
DISTRICT III