



NEW MEXICO DEPARTMENT OF MINERAL
& NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/28/19 Operator Blackhawk energy corp API #30-0 39-27731
Property Name Jic 464-31 Well No. 11 Location: Unit Section 31 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 75 Intermediate Casing 249 Bradenhead 14

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		249		
10 min	0		249		
15 min	0		249		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: H₂S tube pulled showed 0. H₂S on initial blow down.
BH showed 14 psi on gauge, blow down in 26 seconds, followed
by lite fumes through out Test decreasing to almost nothing
by end of Test, BH showed 0 psi after five min shut in with 2 sec
POOF.
By Robert Talamante Witness
Plant/lease operator
(Position)

E-mail address rtalamante@blackhawkenergycorp.com

DISTRICT III