



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

NMOCD

OCT 24 2013
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10.23.19 Operator Tride Energy API #30-0 43-20731

Property Name San Isidro 15 Well No. 7 Location: Unit 7 Section 15 Township 20 Range 3

Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate N/A Casing 18 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead Int	Csg	INTERM Int	Csg	
TIME						
5 min	<u>0</u>		<u>18</u>			
10 min	<u>0</u>		<u>18</u>			
15 min	<u>0</u>		<u>18</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing		
Nothing	☒	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing when opened. Nothing when opened after 5 min shut-in.

By Anthony Brown
A.P.E. C. Pomper
(Position)

Witness Monica Kuehling

E-mail address _____