



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOCd

OCT 23 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10.22.19 Operator Pride Energy API #30-0 43-20895
Property Name San Isidro 5 Well No. 2 Location: Unit B Section 5 Township 20 Range 2
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 12 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>12</u>		
10 min	<u>0</u>		<u>12</u>		
15 min	<u>0</u>		<u>12</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Duff when opened. Nothing when opened
after 5 min shut in

By James Brown
D.P.E.C. Rumpert
(Position)

Witness Monica Kuehling

E-mail address _____