



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/17/19 Operator Enduring Resources API #30-0 43-21325
Property Name Wescovada Unit Well No. #307H Location: Unit Section 19 Township 22N Range 7W
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 403 Intermediate N/A Casing 1038 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	ϕ		1037		
10 min	ϕ		1037		
15 min	ϕ		1037		
20 min					
25 min					
30 min					

Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD ϕ

INTERMEDIATE N/A

REMARKS:

Bradenhead blew down to nothing in approx 10 seconds

By

HSE Tech

(Position)

Witness

E-mail address

JDockter@EnduringResources.com

NMOCD

OCT 24 2019

DISTRICT III

10-22-19