



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/17/19 Operator Enduring Resources API #30-0 43-21326
Property Name West Escavada Unit Well No. #308H Location: Unit 1 Section 19 Township 22N Range 7W
Well Status (Shut-In or Producing) Initial PSI: Tubing 509 Intermediate N/A Casing 1031 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	ϕ		1032			
10 min	ϕ		1032			
15 min	ϕ		1032			
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD ϕ INTERMEDIATE N/A

REMARKS: gas blew down to nothing in approx 2 seconds

By John Doerflinger
HSE Tech
(Position)

Witness _____

E-mail address JDoerflinger@EnduringResources.com

NMOCOD
OCT 24 2019
DISTRICT III

10-22-19