



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 10-18-19 Operator Hilcorp Energy API # 30-0 45-29581

Property Name Tiger Well # 6 Location: Unit D Sec 35 Twn 30N Rge 3W

Land Type:

State \_\_\_\_\_  
Federal \_\_\_\_\_  
Private X \_\_\_\_\_  
Indian \_\_\_\_\_

Well Type:

Water Injection \_\_\_\_\_  
Salt Water Disposal \_\_\_\_\_  
Gas Injection \_\_\_\_\_  
Producing Oil/Gas X \_\_\_\_\_  
Pressure observation \_\_\_\_\_

NMOCD

OCT 24 2019

DISTRICT III

Temporarily Abandoned Well (Y): New TA TA Expires: Failure

Casing Pres. 0 Tbg. SI Pres. \_\_\_\_\_ Max. Inj. Pres. \_\_\_\_\_  
Bradenhead Pres. 0 Tbg. Inj. Pres. \_\_\_\_\_  
Tubing Pres. No tubing  
Int. Casing Pres. \_\_\_\_\_

Pressured annulus up to Unable to test psi. for \_\_\_\_\_ mins. Test passed (failed)

REMARKS: Pressured up to 580psi - lost approx 40psi in 6min - bled off and  
tried again - Pressured up to 560psi - lost approx 20psi in 2min - bled off - FAILED

CIBP 1615' 1000# spring for shut close test col  
8-1-19

By [Signature] Witness [Signature]  
(Operator Representative) (NMOCD)

(Position)

Revised 02-11-02