



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 10-18-19 Operator Hilcorp Energy API # 30-0 45-29702

Property Name Tiger Well # 9 Location: Unit M Sec 26 Twn 30N Rge 13W

Land Type:

State _____
Federal _____
Private X
Indian _____

Well Type:

NMOCD
OCT 24 2019
DISTRICT III

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Yes): New TA TA Expires: 10-18-2024

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. No tubing
Int. Casing Pres. _____

Pressured annulus up to 605 psi. for 30 mins. Test passed/failed

REMARKS: Pressured up to 605psi - holding at 605psi 5min - 605psi 10min - slight drop
at approx 5psi to 600psi at 15min - 600psi 20min - 600psi 25min - 600psi 30min

1696' CIBP 1000# spring 1hr clock/chart 16st cal
8-1-19

By [Signature] Witness [Signature]
(Operator Representative) (NMOCD)

(Position)

Revised 02-11-02