



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-27-19 Operator Black Hawk API #30-0 39-24081

Property Name 458 - Well No. 2 Location: Unit 0 Section 7 Township 30 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>20</u>			Steady Flow
10 min	<u>0</u>		<u>20</u>			Surges
15 min	<u>0</u>		<u>20</u>			Down to Nothing
20 min						Nothing
25 min						Gas
30 min						Gas & Water
						Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH had very little Pool of gas
When opening B-Valve went Dead
in 1 sec.

By Matthew Trujillo
Operator
(Position)

Witness

E-mail address mtrujillo@BlackHawkEnergy.com