



OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district](http://emrdr.state.nm.us/ocd/District%20III/3district)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-20-19 Operator Black Hawk Energy Corp API #30-0 39-24106
Property Name 457 Well No. 1 Location: Unit L Section 9 Township 38 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 1 Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0	/	48		
10 min	0	/	48		
15 min	0	/	48		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

No Pressure when opening BH. Casing
Pressure Held at 48 No pressure on
BH. Good.

By MT
Rumsey / Operator
(Position)

Witness _____

E-mail address _____