



OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district](http://emnrd.state.nm.us/ocd/District%20III/district)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-20-19 Operator Black Hawk Energy API #30-0 39-25786
Property Name 459-20 Well No. 7 Location: Unit 6 Section 20 Township 30 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 25 Intermediate Casing 35 Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>0</u>		<u>35</u>		
10 min	<u>0</u>		<u>35</u>		
15 min	<u>0</u>		<u>35</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>NMOC</u>
Gas	<u>OCT 29 2019</u>
Gas & Water	<u>DISTRICT III</u>
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: BH had no pressure on BHA Casing
held pressure during test.

By Matthew Trujillo
Operator
(Position)

Witness

E-mail address mtrujillo@BlackHawkEnergy.com