OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-10-19 Operator BlackHawK API #30-0 39-26233

Property Name 458-8SJ Well No. 9 Location: Unit K Section 8 Township 31 Range 3

Well Status(Shut-In or Producing) Initial PSI: Tubing 25 Intermediate — Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
5 min	0	—	30		
10 min	0	—	30		
15 min	0	—	30		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

NMOCD
OCT 29 2019
DISTRICT III

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE____

REMARKS: No BH Pressure During test. Casing pressure held Good.

By Matthew Trujillo Witness____

Operator
(Position)

E-mail address MTrujillo@BlackHawkEnerg.com