



NMOC

OCT 29 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

Date of Test 8-6-19 Operator BLACK HAWK API #30-0 39-27801
Property Name Jicarrilla Well No. 13 Location: Unit 460-15 Section 15 Township 30 Range 34
Well Status (Shut-In or Producing) Initial PSI: Tubing 700 Intermediate - Casing 700 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>700</u>		
10 min	<u>0</u>		<u>700</u>		
15 min	<u>0</u>		<u>700</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR - FRESH - SALTY - SULFUR - BLACK -

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE -

REMARKS:

BH had no pressure on it.

By Matthew Trujillo
Operator
(Position)

Witness -

E-mail address mtrujillo@BlackHawkEnergyCorp.com