



NEW MEXICO DEPARTMENT OF ENERGY
AND MINES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-10-19 Operator Black Hawk API #30-0 39-29324
Property Name 459-17 Well No. 24 Location: Unit Section 17 Township 30 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 45 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	/	45		
10 min	0	/	45		
15 min	0	/	45		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

No pressure During test on BH
Casing pressure held good.

By

Witness

(Position)

E-mail address