



OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-27-19 Operator Black Hawk API #30-0 39-29894
Property Name 458-08 Well No. 113 Location: Unit ___ Section 8 Township 30 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 35 Intermediate ___ Casing 100 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>0</u>		<u>100</u>		
10 min	<u>0</u>		<u>100</u>		
15 min	<u>0</u>		<u>100</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE ___

REMARKS: No Pressure on BH. No pressure on casing pressure held good during testing.

By Matthew Trujillo
Operator
(Position)

Witness _____

E-mail address Mtrujillo@BlackHawkEnergy.com