



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

NOV 15 2019

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 11/15/2019 Operator Hilcorp Energy API #30-0 39-30439

Property Name Canyon Largo Unit Well No. 279E Location: Unit I Section 14 Township 25 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing D Intermediate NA Casing 1.0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>0</u>	<u>(</u>	<u>1.5</u>		
10 min	<u>0</u>	<u>(</u>	<u>0.5</u>		
15 min	<u>0</u>	<u>(</u>	<u>0</u>		
20 min		<u>(</u>			
25 min		<u>(</u>			
30 min		<u>(</u>			

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:
BH through 1" valve, Light puff to nothing in 5 sec. Casing connection
had light drip, kept valve closed between readings.

By [Signature]
MSO
(Position)

Witness [Signature]
J. Kelly

E-mail address _____