



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

NMOC

NOV 15 2019

MECHANICAL INTEGRITY TEST REPORT

DISTRICT III

(TA OR UIC)

Date of Test 11/15/2019 Operator Hilcorp Energy API # 30-0 39-30493 39

Property Name Canyon Largo Unit Well # 279E Location: Unit I Sec 14 Twn 25 Rge 6

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. NA Max. Inj. Pres. NA
Casinghead Pres. 0 Tbg. Inj. Pres. NA
Tubing Pres. 0
Int. Casing Pres. NA

Pressured annulus up to 602 psi. for 35 mins. Test passed/failed

REMARKS: 1000 lbs spring, 1 hr clock, 1 hr 1000 lbs chart; last calibrated 8/1/2019.
Started @ 0 psi, pressured up to 602 psi, 5 min 602 psi BHT 0 psi, 10 min 603 psi BHT 0 psi,
15 min 602 psi BHT 0 psi, 20 min 601 psi BHT 0 psi, 25 min 600 psi BHT 0 psi, 30 min
600 psi BHT 0 psi, 35 min 600 psi BHT 0 psi, bled back down 0 psi.

(Operator Representative)

Witness

(NMOC)

(Position)

Revised 02-11-02