



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 31 OCT 2019 Operator F1221 API #30-0 43-20719

Property Name SAN ISIDRO 16 Well No. 10 Location: Unit 2 Section 16 Township 20 Range 3

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	BH	Bradenhead Int	Csg	BRADENHEAD	INTERMEDIATE
TIME					
5 min	0	N/A	0	Steady Flow	
10 min	0		0	Surges	
15 min	0		0	Down to Nothing	
20 min				Nothing	
25 min				Gas	
30 min				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: OPENED THE BRADEN HEAD AND NOTHING
CAME OUT.

By [Signature]

Witness [Signature]

(Position)

E-mail address _____

NMOC
NOV 01 2019
DISTRICT III