



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-27-19 Operator Black Hawk API #30-0 39-26182

Property Name 458 SJ Well No. 2 Location: Unit 0 Section 7 Township 30 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 110 Intermediate Casing 120 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH Int	Csg		Int	Csg
5 min	<u>0</u>	<u>120</u>			
10 min	<u>0</u>	<u>120</u>			
15 min	<u>0</u>	<u>120</u>			
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: BH had no pressure when doing test.
Casing pressure held good

By Matthew Trujillo
Operator
(Position)

Witness

E-mail address mtrujillo@BlackHawkEnergy.com