



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOCD

JAN 10 2020

DISTRICT III

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 1.10.20 Operator Logos Operating API # 30-0 39-06711

Property Name Sicari: 11a114 N Well # 9 Location: Unit 6 Sec 26 Twn 4 Rge 4

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres.
Bradenhead Pres.
Tubing Pres.
Int. Casing Pres.

Tbg. SI Pres.
Tbg. Inj. Pres.

Max. Inj. Pres.

Pressured annulus up to 565 psi. for 30 mins. Test passed failed

REMARKS:

Casing repair: holes from 3632-3800- Composite Plug at
3875-
Testing from 3875 to surface.
dropped to 560 and held- test Passed.

By R. Delgado
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

Contractor
(Position)

Revised 02-11-02

30-039-06711

