



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOC

CHG 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/10/19 Operator Enduring Resources PI #30-0 39-07081

Property Name Rincon Unit Well No. 78 Location: Unit Section Township Range

Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate 672 Casing 66 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min	Ø	672	66	127	64
10 min	Ø	672	66	26	63
15 min	Ø	672	66	6	63
20 min				2	61
25 min				1	60
30 min				1	57

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing		
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE 5

REMARKS:

- Bradenhead puffed after shut-in
- intermediate blew down to steady flow, then ran blow around 15 minutes; not blown down prior to test per request

By John Dockter

Witness Monica Kuehling

HSE ech
(Position)

E-mail address JDockter@EnduringResources.com

- request gas sample

7/30/19