



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOCDO

DEC 16 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12.12.19 Operator Logos CP. LLC API #30-0 45-06621
Property Name Richardson Well No. 2 Location: Unit P Section 11 Township 27 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 04 Intermediate 1A Casing 4 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min	0		0		
25 min	0		0		
30 min	0		0		

Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1A

REMARKS:

Hard puff when opened - Casing fell to 0 in 30 seconds. Light puff when opened after 5 min shut in

By Joan merchan
Lead Operator
(Position)

Witness Monica Luehring

E-mail address _____

Retest in 30 days.
do 24 hr shut in 12.12.19
Check 12.13.19