



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-17-19 Operator BPX API # 3004510258

Property Name Riddle C Ls 3 Location: Unit N Section 29 Township 31 Range 9
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 28 Intermediate Ø Casing 39 Bradenhead 36

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	Ø	42	Ø	Ø	40	✓	
10 minutes	Ø	42	Ø	Ø	40		
15 minutes	Ø	43	Ø	Ø	39		✓
20 minutes	Ø	43	Ø				
25 minutes	Ø	42	Ø			✓	
30 minutes	Ø	41	Ø				
5 minute SI	Ø	40	Ø	Ø	39	NMOCD	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead Ø Intermediate Ø

REMARKS:

Samples taken: BH - 1023, Int - not enough pressure, T 1022, & C - 1025
Whispered down to Vapor in 57 sec. Vapor at 5min Vapor at 10min, Vapor at 15min,
Vapor at 20min, Vapor at 25min, Vapor at 30min. Whisper at end of 5min
shut-in. Intermediate 8 sec light flow till nothing. Compressed Site. No flow at end
of 5min shut-in test for Intermediate.

By Eugenia Hamilton Witness _____
Technician

(Position)