



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCO

DEC 19 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12.18.19 Operator Hilcorp Energy Co API #30-0 4530788

Property Name Ashcroft Slud Well No. 1 Location: Unit B Section 26 Township 29 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 59 Intermediate 0 Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	-3	5	0	4
10 min	0	-3	5	0	4
15 min	0	-4	4	0	4
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	✓
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: BH - Nothing when opened. Nothing when opened after 5 min shut in. Int - Nothing when opened. Nothing when opened after 5 min shut in.

By STEVEN JIMENEZ
SWD OPERATOR
(Position)

Witness Monica Tuckling

E-mail address _____