

Deviation Report

Name of Company	Address	
Burlington Resources Oil & Gas Company	P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number)	Location	Sec. Twn. Rge.
SAN JUAN 28-6 UNIT #98N (30-039-29619)	1330 FNL 2170 FEL	03-027N-006W
Pool and Formation	County	State
BASIN DAKOTA	RIO ARRIBA	NEW MEXICO

(OH)

Depth (ft)

Deviation (degrees)

100	0.75
230	1.00
730	0.25
1,204	0.75
1,677	1.25
2,173	1.00
2,644	1.00
3,143	1.00
3,518	1.00
7,730	1.25



Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Co authorized by said Company to make this report; and that this report was prepared under my supervision and direction facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 11th day of MAY, 2006.

Notary Public in and for San Juan County, New Mexico

My commission expires March 20, 2010.