

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

	Location: Unit P Section 35 Township 3	
Well Status (Shut-In or Producing) Tubing 40	Intermediate Casing 39 Braden	head <u>Ö</u>
OPEN BRADENHEAD AND INTERMEDIATE TO	ATMOSPHERE INDIVIDUALLY FOR 1:	5 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow	
10 minutes	Surges_	
15 minutes	Down to Nothing	
20 minutes	Nothing	
25 minutes	Gas	
30 minutes	Gas & Water	
	Water	1: 12V11
If bradenhead flowed water, check all of the descriptions	that apply below:	
CLEAR FRESH SALTY	SULFURBLACK	JUN 2006 1
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE	Property (1)
By Zriggen Meilate Contract Pumper (Position) E-mail address + 1 Mexil of the All All Maril. Co	Witness	