

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copies to above address)

Date of Test 5/11/06 Operator Dugan Production Corp. API # 30-045-26757  
Property Name Sage Creek #1 Well No. 1 Location: Unit 1 Section 3 Township 22N Range 08W  
Well Status (Shut-In) or Producing Initial PSI: Tubing \_\_\_\_\_ Intermediate \_\_\_\_\_ Casing 4 1/2" Bradenhead 1"

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

	Bradenhead			Interm	
TIME	BH	Int	Csg	Int	Csg
5 minutes	0		44		
10 minutes	0		44		
15 minutes	0		44		
20 minutes					
25 minutes					
30 minutes					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

0"

INTERMEDIATE

REMARKS:

Well has no tubing TA.

By

Luke Dugan

Witness

Switcher

(Position)