NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test	05-16-06	Operator	Dugan l	Production	on Corp.	:API #	30-045	-29216			
Property Name Bisti State		_Well No	90	_Location: Unit	<u>H</u>	_Section _	2 Township		ange 13W		
Well Status(Shut-In or Producing) Initial PSI:		Tubing _	50	_Intermediate	NONE	_Casing	20	_Bradenh <u>ea</u>	d <i>O</i>		
											
OPEN BRA	ADENHEAD AN		DIATE T	ГО АТМС	SPHERE INC	OIVIDUAL	LY FOR	15 MINUTES	EACH		
	Bradenhead Interm						FLOW CHARACTERISTICS				
TIME	BH Int Csg	Int Csg	7			BRAD	ENHEAD	INTERME	DIATE		
5 mintues	0 20		:	Steady Flor	w	_					
10 minutes	0 30		;	Surges							
15 minutes	0 20		1	Down to No	othing						
20 minutes				Nothing		义					
25 minutes] ,	Gas					· · ·	- Sheet	
30 minutes] ,	Gas & Wat	er				- 15 ()	TO WAR	
		•	•	Water					ارکی احی	South C	
									es es		
If bradenhead flowed water, check all of the descriptions that apply below:											
	CLEAR	₹	FRESH_		SALTY	SULFL	JR	BLACK			
5 MINUTE SHUT-IN BRADENHEAD				0	INTE	INTERMEDIATE					
REMARKS:											
					··-						
							 				
							 _				
			-								
By Kake U. Mulline)		iess					
		Switcher			_						
		(Position)									