

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170


[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 5/23/06 Operator Dugan Production Corp. API # 30-045-09337
Property Name Pan American Federal Well No. 1 Location: Unit N Section 24 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 300 Intermediate _____ Casing Ø Bradenhead 33

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	Ø		Ø					
10 minutes	Ø		Ø					
15 minutes	Ø		Ø			Down to nothing		
20 minutes								
25 minutes								
30 minutes								

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE _____

REMARKS:

Well surged for a minute or so then was dead (well has packer)

By


Switcher
(Position)

Witness
