



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-8170
<http://emnr.state.nm.us/ocd/District/III/District.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-14-06 Operator Yatas Petco API #30-0 45-28818
Property Name Ropco 7 Well No. 1 Location: Unit Section 7 Township 29N Range 12-W
Well Status (Shut-In or Producing) Initial PSI: Tubing 10# Intermediate Casing 12# Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Bradenhead Int	Csg	Int	Csg
5 min	0		10#		
10 min	0		10#		
15 min	0		10#		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
<u>Nothing</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

Bradenhead 0 Pressure
Well has Pumping Unit goes to CDP Compressor

By Joe Ferris
Pumper
(Position)

Witness David Dempsey

E-mail address

