



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1030 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://emnr.d.state.nm.us/ocd/District/III/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-1-06 Operator Yates Petroleum API #30-0 45-29096
Property Name Roco 12 Well No. 1 Location: Unit J Section 12 Township 29N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 5# Intermediate Casing 20# Bradenhead 10#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		20#		
10 min	0		20#		
15 min	0		20#		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	10#	30 Sec.
Nothing		
<u>Gas</u>		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: Bradenhead 10# Blew Dead 30 sec
Well is on Pumping Unit going thru CDP compressor

By Joe Ferris
Pumper
(Position)

Witness David Dempsey

E-mail address

