

1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	6/6/2006	Operator	Burlington Resources Oil & Gas
--------------	----------	----------	--------------------------------

Lease Name HUERFANO UNIT Well No 173 Location: U O Sec. 13 Twp. 026N Rge. 010W

Pressure (Flowing) Dwt	Tubing	169	Intermediate	Casing	1	Bradenhead	0
------------	---------	-------	--------	-----	--------------	--------	---	------------	---

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:		BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
	INTERMEDIATE	CASING		
5 Min.		1	Steady Flow	
10 Min.		1	Surges	
15 Min.		1	Down to Nothing	
20 Min.			Nothing	X
25 Min.			Gas	
30 Min.			Gas & Water	
			Water	

If Bradenhead flowed water, check description below:

Clear _____

Fresh _____

Salty _____

Sulfur _____

Black _____

Remarks:

Ending: BH Press.: 0 Intern. Press.

No press on casing...possible packer in hole.

By	BOBBY HEINEN	404
	Lease Operator	
	Position	

Witness



DPNO: 5170901