

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 6-7-06 Operator Dugan Production Corp. API # 30-045-10776
Property Name Cuccia Well No. 1 Location: Unit G Section 14 Township 31N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 340 Intermediate NA Casing 825 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead		Interm		BRADENHEAD		INTERMEDIATE	
	BH	Int	Csg	Int	Csg			
5 minutes	0					Steady Flow	0	NA
10 minutes						Surges	0	NA
15 minutes						Down to Nothing	0	NA
20 minutes						Nothing	0	NA
25 minutes						Gas	0	NA
30 minutes	0					Gas & Water	0	NA
						Water	0	NA

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

No pressure on Bradenhead

By Michael D. Binda Witness _____
Switcher
(Position)

