NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test	te of Test <u>6-1.4-6</u> Operator				Dugan Production Corp.			30-045	-26775			
Property Name		Mary I	_ou	_Well No.	3	Location: Uni	tI	Section	32 To	wnship 24N	Range	e <u>10W</u>
Well Status(Shi	ut-In or Proc	lucing	Initial PSI	Tubing _	25	Intermedia <u>te</u>		_Casing	30	Brade	nh <u>ead</u>	0
OPEN BRAI		O AND		EDIATE 1	го атмс	SPHERE IN	DIVIDUAL	LY FOR	15 MINU	JTES EACH		
	Bradenhea	ad	Interm				FLOW CHARACTERISTICS					
TIME	BH Int	Csg	Int Csg				BRADI	ENHEAD	IN	TERMEDIATE		
5 mintues	0	30			Steady Flov	w						
10 minutes	0	30			Surges							
15 minutes	0	30		1	Down to Nothing					, , ,	_	
20 minutes	0	30		7	†			•				
25 minutes	0	30		7 .	Gas		<u> </u>				_	
30 minutes	0	30			Gas & Wate					550	578	O
oo minates		1001		-	Water					A C	夺 `	100
									'	E OIL	- 200 6	
<u>lf bradenh</u>	ead flow	<u>red w</u>	ater, ch	eck all o	f the de	scriptions	that appl	y belov	<u>v:</u>		and the)No. 15
	(CLEAR		_FRESH		SALTY	SULFU	JR	BLACK	DI	ST. 3	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
5 MINUTE SHUT-IN BRADENHEA				EAD .	0		ERMEDIATE		 -	W. P. S.	55/15/7	
REMARKS:												
											-	
									 -			
		-						# ** *				
			•			· ·						
Ву	wife had					Wit	ness					
	Switcher					_						
	(Position)											