

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copies to above address)

Date of Test 6-13-6 Operator Dugan Production Corp. API # 30-045-26784  
Property Name Calgary Well No. 88 Location: Unit A Section 6 Township 23N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 25 Intermediate \_\_\_\_\_ Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		30		
10 minutes	0		30		
15 minutes	0		30		
20 minutes	0		30		
25 minutes	0		30		
30 minutes	0		30		

FLOW CHARACTERISTICS

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

BRADENHEAD	INTERMEDIATE
X	



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By *Steve Sneed*  
Switcher  
(Position)

Witness \_\_\_\_\_