NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test	6-19-6	Operator <u>[</u>	Dugan Produ	iction Corp.	API #	API# 30-045-27404			
Property Name	Calga	ry v	Vell No. 3	Location:	Unit C	_Section _	6 Township	_23N_Ran	ge <u>10W</u>
Well Status(Shut-In or Producing) Initial PSI:		Initial PSI:	Tubing 50	Intermed	iate	_Casing _	45	_Bradenh <u>ead</u>	0
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes		JRE Interm Int Csg	Steady Surges Down t Nothing Gas Gas & Water	Flow o Nothing g	FLOW	CHARACT	ERISTICS	DIATE JUL 2006	JW. 15
5 MINUTE S REMARKS:		BRADENHEAD		 	SULFU		\$ C-1	DIST.	
Ву	Switcher (Position)				Witness				