

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copies to above address)

Date of Test 6/6/06 Operator Dugan Production Corp. API # 30-045-29112  
Property Name Ohwada Well No. 2 Location: Unit C Section 33 Township 24N Range 9W  
Well Status(Shut-In or Producing) Producing Initial PSI: Tubing 27 Intermediate        Casing 34 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		34			
10 minutes	0		34			
15 minutes	0		34			
20 minutes	0		34			
25 minutes	0		34			
30 minutes	0		34			

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE




**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By  Switcher  
(Position)

Witness \_\_\_\_\_