

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 6-706 Operator Dugan Production Corp. API # 30-045-30247
Property Name Cuccia Com Well No. 90 Location: Unit A Section 14 Township 31N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 500 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0					
10 minutes						
15 minutes						
20 minutes						
25 minutes						
30 minutes						

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
0	N/A
0	N/A
0	NA
0	NA
0	NA
0	NA
0	NA



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Bradenhead Blew Down To nothing in less than 5 seconds

By

Whit D. Bimbat

Witness

Switcher

(Position)