NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

						_										
Date of Test <u>06-08-06</u> Operator															-	
Property Name	<u>Pa</u>	n An	nerica	an Fed	deral	Well No.	2	Location:	Unit	<u>D</u>	_Section	24	Township	_30N_	Range	14W
Well Status(Shi	ut-In o	r Prod	ucing)	Initia	il PSI:	Tubing	110	Intermed	iate N/	4	_Casing	//		_Bradenh	nead —) _
OPEN BRAID TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	DENHEAD AND INTERME PRESSURE Bradenhead Interm BH Int Csg Int Csg			Steady Flow Surges Down to Nothing Nothing Gas Gas & Water			FLOW CHARACT BRADENHEAD			15 MINUTES EACH			107			
					Water									_	No. 15	
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK																
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS:																
															- - -	
By Switcher (Position)									Witness	S					<u>-</u>	