

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)


BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 06-08-06 Operator Dugan Production Corp. API # 30-045-30921
Property Name Humble Kirtland Com Well No. 90 Location: Unit B Section 13 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 105 Intermediate N/A Casing 11 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes						Steady Flow	<u>nothing</u>	<u>N/A</u>
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						<u>Nothing</u>		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By *John R. M. X449*
Switcher
(Position)

Witness _____