

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170


[http://emrnr.state.nm.us/ocd/District III/3district.htm](http://emrnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copies to above address)

Date of Test 06-08-06 Operator Dugan Production Corp. API # 30-045-32200  
Property Name Molly Pitcher Well No. 5 Location: Unit A Section 14 Township 30N Range 14W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 6.5 Intermediate N/A Casing 11 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes						Steady Flow	<u>Nothing</u>	<u>N/A</u>
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						<u>Nothing</u>		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Jordan R. [Signature] #49  
Switcher  
(Position)

Witness \_\_\_\_\_