NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test	06-08-06	Operator	Dugan	Productio	n Corp.		_API#	30-045	-322	56			
Property Name	Big Fi	eld	Well No.	7	_Location:	Unit	<u>M</u>	Section	10	Township	30N	Range	14W
Well Status(Shut-In or Producing) Initial PSI:			Tubing 150 Intermedia			ite <i>N/A</i> Casing		_Casing	22		Bradenhead O		-
OPEN BRADENHEAD AND INTERME PRESSURE Bradenhead Interm TIME BH Int Csg Int Csg 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes			Steady Flow Surges Down to Nothing Nothing Gas				FLOW	CHARAC ENHEAD	HARACTERISTICS				
30 minutes			Gas & Water								, A		*
	Water			V				y 🖺	JUL				
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK													
	CLEAR		_FRESH .		SALTY		SULFU	R	BLAC	κ	\$\frac{\lambda}{2}\rangle_{\rangle}.	: 22/2	M. Sir
5 MINUTE S	SHUT-IN	BRADENHE	AD .		_	INTERN	MEDIATE	-				_	
												- -	
ву	South & N	√ Witcher	49		_	Witness	S					-	

(Position)