UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells	31
RECEIVED 1. Type of Well GAS 070 FARMINGTON II	5. Lease Number NMSF-079731A
2. Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY	7. Unit Agreement Name San Juan 28-4 Unit
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	8. Well Name & Number San Juan 28-4 Unit 33E 9. API Well No. 30-039-29370
4. Location of Well, Footage, Sec., T, R, M 1460' FNL, 1040'FWL, Sec. 33, T28N, R4W, NMPM	10. Field and Pool Blanco Mesaverde/Basin Dakota 11. County and State Rio Arriba Co, NM
Recompletion New Co Subsequent Report Plugging Back Non-Ro Casing Repair Water Final Abandonment Altering Casing Conver Other - Surface Csg Deeper	of Plans Instruction Outine Fracturing Shut off Sion to Injection
13. Describe Proposed or Completed Operations Surface casing was set at 319', instead of 120' (as approve referenced well because previously drilled offset wells in circulation. Therefore, surface csg is set at 319'.	red in APD) on this ndicated loss of
14. I hereby certify that the foregoing is true and correct. Signed Title Regulatory Analyst	Date 7/5/06
(This space for Federal or State Office use) APPROVED BY Original Signed: Stephen Mason	Date JUL 1 1 2006 artment or agency of the lts jurisdiction.

NMOCD &



