

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copies to above address)

Date of Test 7-/1-06 Operator  Property Name Chaco  Well Status(Shut-In of Producing) Initial PSI:			Dugan Production Corn			ADI #	30.045				
									hin 24N	- Dom <i>e</i>	OIA
										•	, <u>ovv</u>
OPEN BRA	DENHEAD AI	ND INTERM	EDIATE T	O ATMC	SPHERE IN	DIVIDUAL	LY FOR	15 MINUTE	ES EACH		
Bradenhead Interm						FLOW CHARACTERISTICS					
TIME	BH Int Cs	g Int Csg	_			BRADI	ENHEAD	INTER	MEDIATE	_	
5 mintues	0 2	-		Steady Flow	<b>_</b>			2500	CHAIN BY	1	
10 minutes	0 2		8	Surges					43°		<u> </u>
15 minutes	0 2	11 1		Down to No	othina				<b>JL <u>Rive</u></b>	· 73	년 네
20 minutes	0 7	<del>-    </del>	<b>-</b>	Nothing					E. T	May	
	6 2							150 ON	LO CONTRACTOR	· (0)	<i>#</i>
25 minutes			7	Gas	-	<del></del>		( p) 6	· · · · · · · · · · · · · · · · · · ·	રું∕્ર	
30 minutes				Gas & Wate	er			- 6.6	(3) 16 m 77	-	
			V	Vater						-	
If bradenh	ead flowed	water ch	ock all of	the de	scrintions (	that anni	v bolov				
<u>II Diaueilli</u>	icau iloweu	water, cir	ECK AII UI	tile de	scriptions (	шас аррі	y Delov	<u>v .</u>			
	CLE	AR	FRESH_		_SALTY	SULFU	JR	BLACK			
	SHUT-IN	BRADENH	EAD _	0	INT	ERMEDIATI	Ē				
REMARKS:											
										-	
										-	
						<u></u>				_	
										_	
		(								_	
Ву	Lan	n Theolog	#72		Wit	ness				_	
		Switche	r								
		(Position)			_						