Form 31	60-5	
(August	1999)	

## UNITED STATES

CIVILED STITLES	
DEPARTMENT OF THE INTERIOR	
BUREAU OF LAND MANAGEMENT	

	FORM APPROVED OMB/NO. 1004-0135 Expires/November 30, 2000
5.	Lease Serial No.

	Explica 140vc
5.	Lease Serial No.
	NMSF080382A

ne and/or No.
M
er Shut-Off I Integrity er ation thereof. rs and zones. in 30 days e filed once erator has
in a

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Farmington Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

OK 200 6/18/03

## Schwerdtfeger #12 1,650' FSL & 990' FEL, Unit I, Sec 17, T-27-N, R-11-W San Juan County, New Mexico

Formation:

West Kutz Pictured Cliffs

Production csg:

4", 10.53# FL-4S csg @ 2,015'. Cmtd w/75 sx cmt w/3%

econolite, 1/4#/sk flocele & 5#/sk gilsonite.

Tubing:

63 jts 2-3/8" tbg, SN & NC. EOT @ 1,972'.

Perforations:

1,946' – 1,970' w/2 JSPF

**Current Status:** 

SI

Purpose:

TA Pictured Cliffs.

- 1) Notify BLM and NMOCD 24 hrs in advance for casing integrity test.
- 2) MIRU pulling unit. ND WH. NU BOP. POOH & LD 63 jts 2-3/8" tbg.
- 3) MIRU WL. TIH & set CIBP @ 1,880' (csg collars @ 1,855' & 1,895'). RDMO WL.
- 4) Load casing w/22 BFW. Pressure test casing and CIBP to 500 psig for 30 minutes. Record test on a chart recorder w/a maximum 2 hr clock & 1,000 psig spring, per NMOCD requirements.
- 5) Blow down well. ND BOP. NU WH. RDMO PU.