



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 8-8-06 Operator Burlington Res API #30-0 45-25583
Property Name McCord B Well No. 1E Location: Unit F Section 23 Township 30 Range 13
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 307 Intermediate N/A Casing 442 Bradenhead 96

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			<u>442</u>		
10 min			<u>442</u>		
15 min			<u>442</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 18 INTERMEDIATE N/A

REMARKS: 1 minute and 40 seconds to blow down

By Chris Haff
MSO
(Position)

Witness Monica Kuehling

E-mail address _____