

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7/12/06 Operator			Dugan	Production	on Corp.	API #	30-045	-07023_			_	
Property Name	Fullerton									28N	Ranç	ge 1
Well Status(Sh	Tubing	0	Intermediate	NA	Casing	180		Bradenh	nead	<u></u>		
OPEN BRAI	DENHEAD AND		DIATE ⁻	ТО АТМС	SPHERE II	NDIVIDUAL	LY FOR	15 MIN	UTES E	EACH		
	Bradenhead					CHARACTERISTICS						
TIME	BH Int Csg	Int Csg	1		_	BRADI	ENHEAD	IN'	TERMED	DIATE	-	
5 mintues	(2) 180			Steady Flow	~						-	
10 minutes	081			Surges	_			_			_	
15 minutes	0 180		<u> </u>	Down to No	othing _	$\overline{}$					_	
20 minutes			_	Nothing							_	
25 minutes				Gas								
30 minutes			Gas & Water								•	
		* 	•	Water	_						•	
<u>If bradenh</u>	ead flowed w	rater, chec	ck all o	f the de	scriptions	that appl	y belov	<u>v:</u>			•	
	CLEAR		FRESH		_SALTY _	SULFL	JR	BLACK_		_		
5 MINUTE SHUT-IN BRADENHEARREMARKS:			AD .	0		NTERMEDIATI						
											- -	
Ву	John	Switcher			v	Vitness					<u>-</u> -	

(Position)