




NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 07-26-06 Operator Dugan Production Corp. API # 30-045-22693
Property Name KR Well No. 7 Location: Unit E Section 20 Township 27N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 6.9 Intermediate N/A Casing 7.8 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 mintues						
10 minutes						
15 minutes						
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

No bradenhead

By  Switcher
(Position)

Witness _____